

KISS-CUT: the top surface has been cut, but there is no gap between labels. When you remove the matrix during the manufacturing process, both labels keeps together and "seems like one" by the printer.